

Jeu de 6 tournevis isolés VDE 1000V TBI TORX

621CS6VDEBTBI



Profils



Description produit


Le jeu comprend :

- 6 tournevis isolés VDE profil TORX (réf 621VDEBTBI) dim TX10, TX15, TX20, TX25, TX27, TX30



Nom du produit	SKU	Article	Dimensions	Quantité
Jeu de 6 tournevis isolés VDE 1000V TBI TORX	617049	621CS6VDEBTBI	TX 10 - TX 30	6
Tournevis isolé VDE 1000V TBI pour vis à empreinte TORX		621VDEBTBI	TX 10, TX 15, TX 20, TX 25, TX 27, TX 30	6

* Les images des produits ne sont pas contractuelles. Toutes les dimensions sont en mm, les poids en grammes.


Utilisation (pictures)




Conception de poignée ergonomique pour la protection des mains



Conception ergonomique de la poignée = confort et protection de la main



Surface maximale au contact de la main = puissance de couple accrue



Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.
- VDE tools that have several parts, have to be assembled correctly before use.
- When working with VDE tools avoid contact with water.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.
- Don't use tools that shows sign of wear and have the second layer of plastic visible.